


Wiring Pinout for TPS-100 and TPS-101 Throttle Position Sensors



- Red = +5V In (4.3V Minimum)
- Black = Ground
- Green = +0.8-4.3V Out